

Important Safety Recall

Gold's Gym Inversion System

Weider Club Inversion System

GGBE0867.0
GGCCBE0867.0



WEBE0878.0



ICON Health & Fitness, Inc. has found that the spring on the long adjustment knob or the adjustment strap may become damaged as a result of use. If the spring becomes damaged, the ankle lock can disengage while the inversion system is inverted, causing a user to fall. This can result in serious head and neck injuries. Additionally, if the adjustment strap is damaged, the strap may break, causing a user to unexpectedly rotate farther than desired.

If you have this product, **stop using it immediately**. To receive a free fix kit for the spring on the long adjustment knob and the strap, contact ICON Health & Fitness, Inc.:

CALL TOLL-FREE:

(866) 506-9095

(8 a.m.–4 p.m. MT, Mon.–Fri.)

ON THE WEB:

www.goldsgympowerflex.com/recall

www.weiderfitness.com/recall

In cooperation with the U.S. Consumer Product Safety Commission

Post until 5/15/2010